

Model Question Paper-3 with effect from 2019-20 (CBCS Scheme)

USN

--	--	--	--	--	--	--	--	--	--

**Fourth Semester B.E. Degree Examination
Material Science and Metallurgy**

TIME: 03 Hours

Max. Marks: 100

Note: Answer any **FIVE** full questions, choosing at least **ONE** question from each **MODULE**.

Module -1			*Bloom's Taxonomy Level	Marks
Q.01	a	Explain the BCC and FCC structure with a neat sketch.	L2	06
	b	Classify the imperfections in crystal structure and explain the line dislocation with a neat sketches.	L2	08
	c	Illustrate the mechanism of diffusion.	L2	04
OR				
Q.02	a	Define unit cell and calculate the APF for HCP unit cell.	L5	08
	b	State and explain the Fick's 1 st and 2 nd Law of diffusion.	L2	08
	c	Explain factors influencing diffusion.	L2	04
Module-2				
Q. 03	a	Explain the plastic deformation by slipping and twinning with a neat figure.	L2	08
	b	Explain stages of fracture with a neat sketch.	L5	08
	c	Explain briefly the SN curve.	L2	04
OR				
Q.04	a	Explain the stages of fatigue failure in a material with a neat figure.	L5	08
	b	Explain various stages of creep deformation with a neat figure.	L5	08
	c	Briefly explain Tilt boundary with a neat figure.	L2	04
Module-3				
Q. 05	a	Explain the Hume Rothery rules for solid solution formation with example.	L2	08
	b	Construct the Iron-Carbon equilibrium diagram and label all regions, phase temperature and mention the invariant reactions.	L6	08
	c	State and briefly explain the Gibbs phase rule.	L2	04
OR				
Q. 06	a	Define solid solution.	L1	02
	b	Construct a phase diagram using the following data and label all the fields. Melting point of Ag = 961°C, Eutectic temperature = 780°C, Min. Solubility of Cu in Ag = 9% at 780°C, Min. Solubility of Ag and Cu = 9% at 780°C, Melting point of Cu = 1083°C, Eutectic composition = 28% Cu, Max Solubility Cu in Ag = 2% at 0°C, Max Solubility Ag in Cu = 0% at 0°C. Determine the following: i. Solidification start and end of temperature for 30% Ag alloy ii. Temperature at which a 15% Cu alloy has 50% liquid phase and 50% solid phase iii. % composition of liquid and solid phase in 20% Ag alloy at 900°C.	L6	08
	c	Explain the construction of TTT curves with a neat figure and label the regions.	L5	10
Module-4				

Q. 07	a	Define and list the objectives of heat treatment process.	L1	06
	b	Distinguish between stress relief annealing and process annealing with a neat diagram.	L4	08
	c	What is hardening? Explain with a neat diagram	L2	06
OR				
Q. 08	a	Explain tempering process with a neat sketch.	L2	08
	b	With a neat sketch, explain Jominy End Quench test.	L2	06
	c	With a neat sketch, explain induction hardening process.	L2	06
Module-5				
Q. 09	a	Outline the composition, properties and application of Low carbon steels.	L2	08
	b	Explain the role of types of matrix and reinforcement materials in composites.	L2	08
	c	Define ceramic and list out its application.	L1	04
OR				
Q. 10	a	Outline the composition, properties and application of grey cast iron.	L2	08
	b	Explain the mechanical properties and applications of composite material.	L2	08
	c	List the advantages and limitations of composite materials.	L4	04

*Bloom's Taxonomy Level: Indicate as L1, L2, L3, L4, etc. It is also desirable to indicate the COs and POs to be attained by every bit of questions.